

[Application menu](#) | [Start Tab](#) | [Edit Tab](#) | [Insert Tab](#) | [Configurator Tab](#) | [View Tab](#) | [Info Tab](#) | [Status Bar](#) | [Selected objects](#) | [During the planning process](#) | [Navigate](#)

Application menu

| | |
|--|------------------|
| Create a new drawing | Ctrl + N |
| Open drawing | Ctrl + O |
| Save the current drawing | Ctrl + S |
| Save the current drawing with a new name | Shift + Ctrl + S |
| Start/Terminate Layout mode | F7 |
| Print dialog | Ctrl + P |
| Print preview | Shift + Ctrl + P |
| Edit document settings | Alt + Enter |
| Configure program settings | F11 |
| Terminate pCon.planner | Alt + F4 |

Start Tab

| | |
|---|-------------------------|
| Paste | Ctrl + V Shift + Einf |
| Copy | Ctrl + C Ctrl + Einf |
| Delete | Ctrl + D Entf |
| Quick Copy | Ctrl + Q |
| Copy image | Ctrl + J |
| Copy Article List [pCon.planner Pro only] | Ctrl + B |
| Insert objects from catalog [pCon.planner Pro only] | F6 |
| Insert objects from pCon.catalog | F3 |
| Insert object from Google 3d Warehouse | F8 |
| Insert object from file (e.g. image) | Ctrl + Shift + I |
| Show Property Editor | F12 |
| Show Layer dialog | F4 |

Edit Tab

| | |
|--------------------|------------------|
| Start Move tool | Ctrl + Shift + V |
| Start Rotate tool | Ctrl + Shift + R |
| Start Scale tool | Ctrl + Shift + L |
| Start Region tool | Ctrl + Shift + G |
| Start Extrude tool | Ctrl + Shift + X |

| | |
|---|------------------|
| Start Mirror tool | Ctrl + Shift + M |
| Start Array tool | Ctrl + Shift + A |
| Start Insert Point tool [pCon.planner Pro only] | Ctrl + Shift + N |
| Start Measure Tape [pCon.planner Pro only] | Ctrl + Shift + T |
| Create reference of the selected objects [pCon.planner Pro only] | Ctrl + Shift + F |
| Create group from selected objects | Ctrl + G |
| Ungroup selected group | Ctrl + U |
| Isolate reference copies [pCon.planner Pro only] | Ctrl + Shift + I |
| Lock selected objects | Ctrl + H |
| Unlock fixed objects | Ctrl + Shift + H |
| Show Property Editor | F12 |

Insert Tab

| | |
|--|------------------|
| Insert objects from catalog [pCon.planner Pro only] | F6 |
| Insert objects from pCon.catalog | F3 |
| Insert object from Google 3d Warehouse | F8 |
| Insert object from file (e.g. image) | Ctrl + Shift + I |

Configurator Tab

| | |
|--|----------|
| Insert objects from catalog [pCon.planner Pro only] | F6 |
| Copy Article List [pCon.planner Pro only] | Ctrl + B |

View Tab

Render

| | |
|--|------------|
| Show the drawing in wireframe representation | Shift + F1 |
| Show the drawing in hidden line representation | Shift + F2 |
| Show the drawing in colored representation | Shift + F3 |
| Show the drawing in conceptual representation | Shift + F4 |
| Show the drawing in shaded representation | Shift + F5 |
| Show the drawing in realistic representation | Shift + F6 |

Projection

| | |
|--|-------------------|
| Show the drawing in the perspective view | Ctrl + Shift + F1 |
| Show the drawing from front | Ctrl + Shift + F2 |
| Show the drawing from top | Ctrl + Shift + F3 |

| | |
|--|--------------------|
| Show the drawing from left side | Ctrl + Shift + F4 |
| Show the drawing from right side | Ctrl + Shift + F5 |
| Show the drawing from behind | Ctrl + Shift + F6 |
| Show the drawing from bottom-up | Ctrl + Shift + F7 |
| Show the drawing from north east direction | Ctrl + Shift + F8 |
| Show the drawing from north west direction | Ctrl + Shift + F9 |
| Show the drawing from south east direction | Ctrl + Shift + F10 |
| Show the drawing from south west direction | Ctrl + Shift + F11 |

Camera

| | |
|--------------------------------|----------------------|
| Zoom into view | Ctrl + + |
| Zoom out of view | Ctrl + - |
| Zoom view to extents | Ctrl + Space |
| Zoom view to selection extents | Shift + Space |
| Zoom all viewports to extents | Shift + Ctrl + Space |

Viewports

| | |
|---|-----------|
| Switch to single viewport | Ctrl + F1 |
| Split the screen horizontally in two viewports | Ctrl + F2 |
| Split the screen vertically in two viewports | Ctrl + F3 |
| Split the screen in four viewports | Ctrl + F4 |
| Split the screen in one big and one small view | Ctrl + F5 |
| Split the screen in one big and three small viewports | Ctrl + F6 |

Info Tab

| | |
|-------------------------|----|
| Go to pCon.planner help | F1 |
|-------------------------|----|

Status Bar

| | |
|-----------------------------|----|
| Enter/Leave Fullscreen mode | F5 |
|-----------------------------|----|

Selected objects

| | |
|--|----------|
| Allows to select multiple objects: after selecting an objects press Ctrl and select the next object | Ctrl |
| Select all objects in the drawing | Ctrl + A |
| Invert current selection | Ctrl + I |
| Unselect current selection | Esc |

During the planning process

| | |
|--|------------------|
| Pressing the Alt key while drawing a wall switches the wall end point | Alt |
| Pressing the Alt key while moving an object creates a reference of the selected object | Alt |
| Pressing the Ctrl key while moving creates a copy of the selected object | Ctrl |
| Pressing the Ctrl key while drawing a wall switches the wall orientation | Ctrl |
| Move the reference point (UCS) | Space |
| Rotate reference point (UCS)/Set direction of the World Coordinate System (WCS) | V |
| Repeat insertion of the last inserted element | F2 |
| Cancel current work step | Esc |
| Undo the last operation | Ctrl + Z |
| Redo the last undo operation | Shift + Ctrl + Z |
| While applying tools like rotate or scale the Tab key let's you switch between the shown values | Tab |
| Lock/Unlock axis | Shift |
| Enable/Disable Axis Snap | G |
| Enable/Disable Object Snap | H |
| Pressing the S key while drawing walls opens the wall settings dialog [pCon.planner 6 Pro only] | S |

Navigate

| | |
|--|-------|
| Allows moving downward in the projection Perspective | F |
| Allows moving upward in the projection Perspective | R |
| Pressing Shift while using the PAN changes the layer the panning is performed | Shift |
| Moving forwards in the projection Perspective | W |
| Moving leftwards in the projection Perspective | A |
| Moving backwards in the projection Perspective | S |
| Moving rightwards in the projection Perspective | D |
| Quit current navigation mode | Esc |